

» Product Change Notice (PCN) «

PCN

1101-1

Title

FW Update (BMC: v2_44_6, BIOS: 2.08)

Product

KTC5520/EATX

Issue Date

February 8th, 2011

Document Revision

1.0

Documentation and Contact Resources

For all documentation, please contact technical support.

Contact Information:

Kontron Canada, Inc.

4555 Rue Ambroise-Lafortune
Boisbriand, Québec, Canada
J7H 0A4
Tel: (450) 979-5320
(800) 354-4223
Fax: (450) 437-8053
E-mail: support@ca.kontron.com

Visit our web site at: www.kontron.com

© 2010 Kontron, an International Corporation. All rights reserved.

The information in this PCN is provided for reference only. This PCN may contain or reference information and products protected by copyrights or patents and do not convey any license under the patent rights of Kontron, nor the rights of others.

Kontron is a registered trademark of Kontron. All trademarks, registered trademarks, and trade names used in this PCN are the property of their respective owners. All rights reserved. Printed in Canada. This PCN contains information proprietary to Kontron.

Kontron reserves the right to make changes without notice in product or component design as warranted by evolution in user needs or progress in engineering or manufacturing technology. Changes that affect the operation of the unit will be documented in the next revision of this PCN.

Table of Contents

PCN Revision History.....	3
Description of change.....	4
Change classification.....	4
Impact on compatibility and recommended actions	4

PCN Revision History

Revision	Issue Date	Description
1.0	February 8 th , 2011	First release of this document

Description of change

New BMC release 2_44_6:

1. Add BMC IP address in Virtual KVM window headline.
2. Modification where made to ensure that the Web management login page doesn't stay in cache.
3. FIX: SOL fails to achieve a connection after ~494 successful sessions have been connected and closed.

New BIOS release 2.08:

1. The feature 'Restore on AC power lost' now behaves as expected when the option 'Last state' is selected.
2. FIX: With some hard drives configuration and a third party SAS/SATA Raid PCIe cards, a corruption in the BIOS IPLD table was preventing the OS from booting.

Change classification

This Firmware update is not mandatory.

Impact on compatibility and recommended actions

It is recommended to update boards with the previous BMC and BIOS firmware as they will gain from the added features and fixes listed above.

Firmwares are field upgradeable. Use the BMC and BIOS files found on the product's web page:

ftp://ftp.kontron.ca/Support/Products/Motherboard/KTC5520_EATX/KTC5520_EATX.html